

Under Review Notification

Raised By: Victoria Seib

Product #: D212-803

Date: 13.07.11

Product Name: Left-Hand Pilot in Command

Part Number	Drawing/Document	"Y" or "N" Required								Instructions
		HOLD SHIPMENT	Red Tag/Quarantine Stock	Advise customers	Stop Production	Re-Work Stock	IPP Under Review	Blue File Under Review	ECN # Required	
D4410-041	D4410 Rev. B	N	N	N	Y	N	Y	N	13-591	OK to ship existing stock
D4410-043	D4410 Rev. B	N	N	N	Y	N	Y	N	13-591	OK to ship existing stock
D4410-045	D4410 Rev. B	N	N	N	Y	N	Y	N	13-591	OK to ship existing stock
D4410-1	D4410 Rev. B	N	N	N	Y	N	Y	N	13-591	OK to ship existing stock
D4410-15	D4410 Rev. B	N	N	N	Y	N	Y	N	13-591	OK to ship existing stock

Description of issue:

- REF CIR13-23 and CIR13-25
- D4410-1 will have a new cut to avoid hitting the pilot's leg
- D4410-15 will be adjusted to accommodate the new cut on D4410-1
- OK to ship existing stock of D212-803
- D4410-043/-045 will incorporate a new part, D4410-17
- D4410-041 will incorporate the revised D4410-1
- D4410-041/-043/-045 will incorporate the revised D4410-15

Distribution:

General Manager
Production Manager
Director Quality Assurance
Design Manager

Chief Engineer
Engineering Project Managers
Engineering Clerk
Marketing